

Service

Category Vehicle Interior

Section Interior Panels/Trim Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 – 2011	Camry, Camry HV	

Introduction

Some 2007 – 2011 model year North American Produced (NAP) Camry and Camry HV vehicles may exhibit a rattle noise from the left or right front doors or door panel area. This may be due to a loose plastic cover on the door panel energy absorption pad. Use the following procedure to correct this condition.

Production Change Information

This TSB applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	ENGINE	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
	4 cyl	TMMK Line 1	4T1BF3EK#BU189038
		TMMK Line 2	4T1BF3EK#BU654667
Camry		SIA	4T4BF3EK#BR151092
	Ve	TMMK Line 1	4T1BK3EK#BU126210
	V6	TMMK Line 2	4T1BK3EK#BU620728
Camry HV	HV	TMMK Line 2	4T1BB3EK#BU139153

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
NV1037	R & R Front Door Trim Panel Assembly	0.4	676#0-06###-##	91	15
Combo A	Repair Procedure	0.2	676#0-06###-##	91	15

APPLICABLE WARRANTY

- This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Required Tools & Equipment

REQUIRED EQUIPMENT	QUANTITY
Hot Glue Gun	1

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Plastic Pry Tool Set*	00002-06000-01	1

^{*} Essential SST.


NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Repair Procedure

1. Disengage the 2 clips and remove the front door lower frame bracket garnish.

Figure 1.




TOYOTA

Repair Procedure (Continued)

2. Remove the front door inside handle bezel plug.

Using a plastic pry tool or equivalent, disengage the 3 claws, and remove the front door inside handle bezel plug.

Figure 2.




1	Claw
2	Plastic Pry Tool

3. Remove the assist grip cover.

Using a plastic pry tool or equivalent, disengage the 6 claws and remove the assist grip cover.

Figure 3.




1	Claw
2	Plastic Pry Tool

TOYOTA

Repair Procedure (Continued)

- 4. Remove the courtesy light assembly.
 - A. Using a plastic pry tool or equivalent, disengage the claw and remove the courtesy light assembly.
 - B. Disconnect the connector.


Figure 4.



1	Claw
2	Plastic Pry Tool

- 5. Remove the front door trim board sub-assembly.
 - A. Remove the 3 screws and clip A.

Figure 5.



Α	Clip A
1	Clip (9)


B. Using a plastic pry tool or equivalent, disengage the 9 clips.

Repair Procedure (Continued)

C. Pull up the front door trim board in the direction Figure 6. indicated by the arrow.

NOTICE

If door panel is not removed as instructed, damage to door panel may occur.



I	1	Claw
Ī	2	Reference Boss


- D. Disengage the reference bosses from the front door panel.
- E. Raise the front door trim board to disengage the 4 claws and remove the front door trim board together with the front door inner glass weatherstrip.



Repair Procedure (Continued)

F. Disengage the 2 claws and disconnect the front door inside handle sub-assembly.

Figure 7.




1 Claw

6. Remove the front door inner glass weatherstrip.

Using a screwdriver, disengage the 4 clips as shown in the illustration and remove the front door inner glass weatherstrip from the front door trim board.

Figure 8.



1 Clip

Repair Procedure (Continued)

7. Inspect for loose energy absorption pad cover.

NOTE

If energy absorption pad cover is not loose, STOP. This TSB does NOT apply. Continue with normal diagnostic procedures for unidentified interior noise. Follow steps 12 – 19 to reassemble the vehicle.

Figure 9.



8. Remove remaining adhesive from the energy absorption pad and cover.

Figure 10.



9. Scuff the energy absorption pad surface.

TOYOTA

Repair Procedure (Continued)

10. Using a standard hot glue gun, apply hot glue to both the plastic cover and energy absorption pad.

NOTE

Allow glue gun to reach maximum temperature before applying glue to maximize adhesion.

Figure 11.



Figure 12.




11. Press the two pieces together and apply pressure for approximately 2 minutes.

NOTE

Allow part to fully cool before reinstalling into vehicle.

12. Install the front door inner glass weatherstrip by engaging the 4 claws.

Figure 13.



1 Claw


13. Reconnect the front door wire assembly (for driver side).



Repair Procedure (Continued)


14. Engage the 2 claws and install the front door inside handle sub-assembly.

Figure 14.



- 1 Claw
- 15. Install the front door trim board sub-assembly.
 - A. Connect each connector.
 - B. Align the front door trim board reference boss and engage the 4 clips of the front door inner glass weatherstrip.

Figure 15.



1	Reference Boss
2	Clip

TOYOTA

Door Trim Panel Rattle


Repair Procedure (Continued)

C. Engage the 9 clips and install the front door trim board to the front door panel.

NOTICE

Do NOT use excessive force when engaging the clips.


Figure 16.



1	Clip (9)
Α	Clip A

- D. Install the 3 screws and clip A.
- 16. Install the courtesy light assembly.
 - A. Connect the connector.
 - B. Engage the claw and install the courtesy light assembly.


Figure 17.



Repair Procedure (Continued)

17. Install the assist grip cover by engaging the 6 claws.


Figure 18.



1 Claw

18. Install the front door inside handle bezel plug by engaging the 3 claws.

Figure 19.



1 Claw

Repair Procedure (Continued)

19. Install the front door lower frame bracket garnish by engaging the 2 clips.

Figure 20.

Clip

20. Test drive the vehicle to confirm that no abnormal noise is present.