#### **DISTRIBUTE TO:**

☑ Service Manager☑ Warranty Administrator



## Warranty Policy Bulletin

No.: POL12-03 Date: 8/1/12 Page: 1 of 4

**REVISED 9/20/12** 

SUBJECT: CUSTOMER SUPPORT PROGRAM (ZTT): WARRANTY ENHANCEMENT FOR SUN VISOR ASSEMBLIES AND SUN VISOR BRACKETS ON CERTAIN 2007- 2011MY CAMRY AND CAMRY HYBRID VEHICLES

#### Background

Toyota has received a number of reports regarding sun visors in certain 2007 to 2011 model year Camry and Camry Hybrid vehicles. In these cases, the sun visor may slowly rotate downward. In a limited number of cases, the sun visor may become detached.

#### **Applicability**

The Sun Visor Assembly and Sun Visor Bracket are covered by Toyota's New Vehicle Limited Warranty for 3 years or 36,000 miles (whichever occurs first). However, Toyota is announcing a Customer Support Program (CSP) to cover the replacement of the Sun Visor Assembly and/or Sun Visor Bracket for *7 years* from the date-of-first-use (regardless of mileage) for the condition described above.

Please verify VIN applicability for this CSP by checking TIS before completing any repairs.

Please note that damage incurred from abuse, an accident and/or crash, vandalism or other similar events is not covered by the New Vehicle Limited Warranty or this Warranty Extension.

### **Applicable VIN Ranges**

Please refer to page 2 for applicable VIN ranges.

# **Applicable VIN Ranges (continued)**

| Model           | WMI | MY   | VDS   | Start Serial | Finish<br>Serial |
|-----------------|-----|------|-------|--------------|------------------|
|                 | 4T1 | 2007 | BB46K | U001025      | U030790          |
|                 |     |      | BE46K | U001025      | U730108          |
|                 |     |      | BK46K | U001023      | U560047          |
|                 |     | 2008 | BB46K | U029356      | U062522          |
|                 |     |      | BE46K | U190003      | U793305          |
|                 |     |      | BK46K | U053666      | U576879          |
|                 |     | 2009 | BB46K | U061175      | U111424          |
|                 |     |      | BE46K | U260017      | U920877          |
| Commund         |     |      | BK46K | U073252      | U596843          |
| Camry and       |     | 2010 | BB3EK | U109087      | U126215          |
| Camry<br>Hybrid |     |      | BF3EK | U001012      | U581179          |
|                 |     |      | BK3EK | U097661      | U609470          |
|                 |     | 2011 | BB3EK | U126216      | U126404          |
|                 |     |      | BF3EK | U581180      | U581649          |
|                 |     |      | BK3EK | U609471      | U609519          |
|                 | 4T4 | 2007 | BE46K | R001029      | R011624          |
|                 |     | 2008 | BE46K | R010583      | R047779          |
|                 |     | 2009 | BE46K | R045380      | R139848          |
|                 |     | 2010 | BF3EK | R001023      | R087509          |
|                 |     | 2011 | BF3EK | R086081      | R086082          |

## **Claim Submission**

| Claim Type        | Op. Code | Description   | Labor Time     |
|-------------------|----------|---|----------------|
| Repair<br>Program | 2705FA   | Replace Sun Visor Assembly (1 or 2 Sides)   | 0.2 hr/vehicle |
|                   | 2705FB   | Replace Sun Visor Bracket<br>or<br>Replace Sun Visor Bracket & Assembly<br>(1 or 2 Sides) | 0.4 hr/vehicle |

<u>Note</u>: If the vehicle is still under the New Vehicle Limited Warranty, submit the repair as a **regular** warranty claim.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

## **Replacement Parts**

All parts replaced for this repair are subject to warranty parts recovery.

| Part Number    | Description    | Vanity<br>Lamp | Trim Color | Qty | Condition<br>(Case)                       | Applicable<br>TSB                    |
|----------------|----------------|----------------|------------|-----|---|--------------------------------------|
| 04002-30106-B0 | Visor Assy, RH | No             | Gray       | 1   | Will Not<br>Retain<br>Desired<br>Position | Repair Manual<br>and<br>T-SB-0093-09 |
| 04002-30106-E0 |                | No             | Tan        | 1   |   |                                      |
| 04002-30306-B0 |                | Yes            | Gray       | 1   |   |                                      |
| 04002-30306-E0 |                | Yes            | Tan        | 1   |   |                                      |
| 04002-30506-B0 | Visor Assy, LH | No             | Gray       | 1   |   |                                      |
| 04002-30506-E0 |                | No             | Tan        | 1   |   |                                      |
| 04002-30706-B0 |                | Yes            | Gray       | 1   |   |                                      |
| 04002-30706-E0 |                | Yes            | Tan        | 1   |   |                                      |



The following parts only require replacement in the limited case there is damage to the sheet metal which retains the sun visor mounting clips.

| Parts Number | Description   | Trim Color | Qty | Condition<br>(Case)                                    | Applicable<br>TSB |
|--------------|---------------|------------|-----|--|-------------------|
| 04009-04133  | Visor Bracket | Gray       | 1   | Loose or<br>Broken Sun<br>Visor<br>Mounting<br>Bracket | T-SB-0284-09      |
| 04009-04233  | Kit, RH       | Tan        | 1   |  |                   |
| 04009-04333  | Visor Bracket | Gray       | 1   |  |                   |
| 04009-04433  | Kit , LH      | Tan        | 1   |  |                   |
| 08231-00801  | Noise Kit     |            | 1   |  |                   |

<u>Note</u>: Toyota warranty will require photo documentation of the damaged sheet metal be attached to the R.O. for all repairs requiring the above Visor Bracket Kit.

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

### <u>Customer-Paid Repairs or Replacement of Components</u>

If a customer has previously paid for the repair or replacement of the Sun Visor Assembly and/or Sun Visor Bracket to address the condition described above, please have them mail a copy of the repair order, proof-of-payment, and proof-of-ownership to the following address for reimbursement consideration:

Toyota Motor Sales, U.S.A., Inc.
Customer Experience Center, WC10
19001 South Western Avenue
Torrance, CA 90509

The customer name, address, and telephone number(s) should be included in the request. The customer should allow 4-6 weeks for processing.