



## Technical Service BULLETIN

December 23, 2003

Title:

### OIL PRESSURE GAUGE READS LOW

Models:

'01 – '04 Sequoia & '00 – '02 Tundra

ELECTRICAL  
EL017-03

#### TSB UPDATE NOTICE:

This TSB updates EL006–03. TSB EL006–03 is now obsolete and should be discarded.

**Introduction** Some customers with Sequoia or Tundra vehicles may encounter an oil pressure gauge that reads abnormally low at idle. An updated oil pressure sender has been created to address this condition.

- Applicable Vehicles**
- **2001 – 2004** model year **Sequoia** vehicles produced **BEFORE** the Production Change Effective VINs shown below.
  - **2000 – 2002** model year **Tundra** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

#### Production Change Information

MODEL		PRODUCTION CHANGE EFFECTIVE VIN
Sequoia	2WD	5TDZT3#A#4S209375
	4WD	5TDBT4#A#4S208662
Tundra		5TB#T##1#2S314095

#### Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
83520–35020	83520–34020	Gauge, Oil Pressure Sender	1

- Repair Procedure**
1. Replace the Oil Pressure Sender.
  2. Verify proper operation of the Oil Pressure Gauge.

#### Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL2010	R & R Oil Pressure Sender Gauge	0.3	83520–35020	73	99

#### Applicable Warranty\*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

